

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



Chun-Pok Leung, Reg. No. 41,405 (650)326-2400
Titled: Dual Piston Rotary Valve
Inventor: Douglas B. Dority
Filed: October 15, 2003 Dckt. No. 021966-000100US
Sheet 1 of 19




Fig. 1




Fig. 2






Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11A




Fig. 11B




Fig. 11C




Fig. 11D




Fig. 11E




Fig. 11F




Fig. 11G




Fig. 11H




Fig. 11I




Fig. 11J




Fig. 11K




Fig. 11L



+



Fig. 11N




Fig. 11 O




Fig. 11 P




Fig. 11Q




Fig. 11R




Fig. 11S




Fig. 12




Fig. 13




Fig. 14




Fig. 15






Fig. 16